



# LavoDose Metering Tip Chart

		Flex Gap			
		1 GPM		3.5 GPM	
Standard Metering Tip	Tip Color	Oz/Gal	Ratio	Oz/Gal	Ratio
	No Tip	50	2:1	22	6:1
	Grey	49	3:1	21	6:1
	Black	44	3:1	20	6:1
	Beige	32	4:1	14	9:1
	Red	20	6:1	9	12:1
	White	13	10:1	6	20:1
	Blue	12	12:1	5	24:1
	Tan	9	14:1	4	32:1
	Green	6	20:1	2	64:1
	Orange	4	32:1	1.8	70:1
	Brown	3.5	36:1	1.5	80:1
	Yellow	3.0	40:1	1.3	96:1
	Aqua	2.0	64:1	1	128:1
	Purple	1.0	128:1	0.5	256:1
Pink	0.7	182:1	0.4	320:1	
Clear	No hole				

		Air Gap			
		1 GPM		4 GPM	
Standard Metering Tip	Tip Color	Oz/Gal	Ratio	Oz/Gal	Ratio
	No Tip	39	2:1	16	6:1
	Grey	39	3:1	16	8:1
	Black	38	3:1	13	10:1
	Beige	31	4:1	11	12:1
	Red	22	6:1	9	15:1
	White	15	8:1	6.2	20:1
	Blue	12	12:1	6	22:1
	Tan	9	14:1	5	25:1
	Green	7	20:1	3.2	36:1
	Orange	6	24:1	2.4	50:1
	Brown	5	28:1	2	64:1
	Yellow	4	32:1	1.8	70:1
	Aqua	3	44:1	1.5	83:1
	Purple	2	64:1	1	128:1
Pink	1	128:1	0.5	256:1	
Clear	No hole				

Ultralean Tip	Lime	.50	256:1	.25	512:1
	Burgundy	.40	333:1	.20	625:1
	Pumpkin	.25	512:1	.15	833:1
	Copper	.20	625:1	.10	1250:1

Ultralean Tip	Lime	.51	256:1	.25	512:1
	Burgundy	.40	320:1	.17	769:1
	Pumpkin	.30	425:1	.13	1000:1
	Copper	.29	450:1	.09	1429:1